



BUILDING SAFTY/FITNESS CERTIFICATE


The building of S.D. Public Model School Sansar Puri Terrace  
(H.P.) <sup>been</sup> has inspected by me with the concerned junior Engineer. The building has neither  
Tehsil Jaswan Distt. Kangra (H.P.)  
been designed nor constructed by this Department. No earthquake resistant norms have  
been adopted for this building. No structure drawings approved by the competent Govt.  
Agency have been produced. The structure is Non Engineering structure. Hence the  
structural safety of this building cannot be ensured specially from earthquake point of view.  
The year of construction of this building, is also not known. This department will not be  
responsible for any type of loss of life and property etc. if this structure fails under any  
circumstances. However as per visual inspection the building appears to be safe at present  
only.

Dated:-

Place:- Dada Siba

  
Junior Engineer  
HPPWD Sub-Division,  
Dada Siba

  
Assistant Engineer  
Dada Siba Sub-Division  
HPPWD Dada Siba (B & R)  
Dada Siba.

  
Executive Engineer,  
HPPWD Division,  
Delhra.

  
Executive Engineer  
Kotla Behar Division  
HPPWD Kotla Behar